Work Orde July 14, 2009 10		0248										Page 1
Revision ID:	D2604-2 B Console Side	RH, 407 Console		Accept					Setup	Start Stop	1 10 0 14 0 1	
Start Date: Required Date: Reference:	7/15/09 7/15/09	Start Qty: 6.00 Req'd Qty: 6.00			Cust Item I Customer:	D:						
Approvals:		an: MF	Date: <u>0</u> 9 - 07- 5	Tooling: SPC (Y/N):		ite:			Run	Start Stop		
Sequence ID/ Work Center II		Operation Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	t Rej Qty	•	Reject Number	Insp. Stamp
Draw Nbr D2604	Rev	vision Nbr v B		0.00					· - · · · - · - · - · - · - · - · - · -	· · ·		
Waterjet FLOW CNC Waterje	et	FLOW WATER JET Memo 1-Cut as per Deburr if ne	Dwg D2604 □Dwg Rev: cessary	0.00	<u>B</u> [12-			B	9-	8-(?)	
QC Quality Control		QC2- Inspect parts off m	achine FAI/FAIB	0.00				ŀВ	9-8	<u> </u>		

120

QC8- Inspect parts - second check

QC

Memo

Quality Control

- a	Dart	Aer	os	pace	Ltd
-----	------	-----	----	------	-----

W/O:			WO	RK ORDER CHANG	ES			
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							1100 Migi	
								
							i	
Part No	:	PAR #:	Fault Categ	jory:	NCR: Yes	No DQA :	Date: _	
		solution:						
NCR:		1	WORK ORDE	R NON-CONFORMA	NCE (NCR)		
DATE	STEP	Description of NC		Corrective Action Section		Verification	1 Approval	Approval
	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
		•						
				,				
						100		

^{*}NOTE: Date & initial all entries

July 14, 2009 10:39:57 AM

Page 2

Item ID:

D2604-2

Accept

Setup Start

Stop



Revision ID:

В Console Side RH, 407 Console Item Name:

Start Date:

Required Date: 7/15/09

7/15/09

Start Qty: 6.00

Req'd Qty: 6.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: _____

Date:

Tooling:

Run

Start

Stop



QC:

Date: _____

SPC (Y/N):

Date: _____

Accept Oty

Reject

Insp.

130

Sequence ID/

Work Center ID

Brake NC

Brake NC

Operation Description

NC BRAKE

Set Up/ **Run Hours** Draw Number

Draw Rev.

Plan Code

Oty

12 0

Reject Number Stamp

Memo

Deburr if necessary ☐ Form as per Dwg D2604

0.00

0.00

SB 09/08/17

140

QC5- Inspect part completeness to step on W/O

=> Soylosliz

Quality Control

Chemical Conversion Coat per QSI005 4.1

0.00

0.00

mp 09/08/18

150

HandFinish Hand Finishing

Memo

Memo

Dart Aerospace Ltd

W/O:			W	ORK ORDER CHANG	ES					
DATE	STEP	PRO	OCEDURE CHA	NGE	В	у	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							-			
Part No	•	PAR #:	Fault Cate		NCR:	Yes N	lo DQA	:	Date:	
		esolution:								
NCR:			WORK ORD	ER NON-CONFORM	ANCE (I	NCR)	-			
DATE	STEP	Description of NC			tion B		Verifica	ıtion	Approval	Approval
	SILI	Section A	Initial Chief Eng	Action Description Chief Eng		ign & Date	Section		Chief Eng	QC Inspector
•										
·										
 ,										

В



July 14, 2009 10:39:57 AM

Required Date: 7/15/09

Item ID:

D2604-2

Accept

Setup Start

Stop



Revision ID:

Console Side RH, 407 Console Item Name:

Start Date:

7/15/09

Start Qty: 6.00

Req'd Qty: 6.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Rev.

Run

Start

Stop



Sequence ID/

QC:

SPC (Y/N): Date:

Date:

Draw

Code

Plan Accept Qty

Reject Qty

Reject Insp. Number Stamp

Work Center ID

160

Quality Control

Operation Description

QC3- Inspect Part Finish

Memo

0.00

Run Hours

0.00

Set Up/

Draw

Number

\$ 09-08-18

170

Packaging

Packaging

Identify as per dwg & Stock Location 5+1)

Memo

0.00

0.00

180

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

09/08/24 9 MF 09-08:20

Dart Aerospace	Ltd
----------------	-----

W/O:			W	ORK ORDER CHANG	ES		•		
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						···			
Part No	•	PAR #:	Fault Cate	egory:	NCR: Yes	No DQ	A:	Date:	
	R	esolution:	Disposition	on:	_ QA: N/C C	losed:		Date: _	
NCR:		V	VORK ORD	ER NON-CONFORMA	NCE (NC	₹)			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Description	Sign	& Secti	cation on C	Approval Chief Eng	Approval QC Inspector
			Criter Erig	Chief Eng	Date				

July 14, 2009 10:39:56 AM

Work Order ID: 50248

Parent Item:

D2604-2RevB

Parent Item Name: Console Side RH, 407 Console

Comments:



Start Date: 7/15/09

Required Date: 7/15/09

Start Qty: 6.00

Required Qty: 6.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
M2024T3S.040		Purchased	No			100	sf	77.9100	8.5086			
										19-		

2024-T3 .040 sheet

<u>Warehouse</u>	Loc Qty	Loc Code		
Location				
Main Warehouse				
MAT	77.91			
110337	6.4			
111381	4			
111786	67.51			
112331			112331	B 9.8-12



Dart	Aeros	pace	Ltd

W/O:			V	ORK ORDER CHANG	iES					
DATE	STEP	PROC	CEDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No		PAR #:								
	R	esolution:							Date: _	
NCR:		W	ORK OR	DER NON-CONFORM	ANCE	(NCR))			
DATE	STEP	Description of NC Section A	Initial	Corrective Action Sect Action Description	ion B	Sign &	Verifica Section		Approval Chief Eng	Approval QC Inspector
			Chief Eng	Chief Eng		Date	Geetion		Office Eng	QO Mapector

							İ		-	
										:

DART AEROSPACE LTD	Work Order: 5024	3
Description: Console Side	Part Number: D2604	1-2
Inspection Dwg: D2604 Rev: A1	Page 1	of 1

•	FIRST ARTICLE INSPECTION CHECKLIST								
		X First A	rticle [Prof	totype				
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	С	omments		
10.700	+/-0.010	10.698	de						
12.000	+/-0.010	11.997	×						
Ø0.098	+0.005/-0.000	101	>	<u> </u>	-				
R0.125	+/-0.010	1135	x -						
4.062	+/-0.010	4.067	6						
				···					
	-								
		-	,		1				
		· · · · · · · · · · · · · · · · · · ·		····			- 		
				-			<u>-</u>		
15									
- 1			-						
	1								
Measured by:	IB.	Audited by	: \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		Prototype App	oroval:	N/A		
Date:	9-8-1)	Date	: 07/1/1/	3		Date:	N/A		
				∠ l			l		

Rev	Date	Change	Revised by	Approyed
Α	05.04.25	New Issue	KJ/JLM A	
			· //	

Dart Ae	rospace	e Ltd						4
W/O:			WO	RK ORDER CHANGE	S			
DATE	STEP	PRO	PROCEDURE CHANGE				Approval Chief Eng / Prod Mgr	Approval QC Inspector
								,
Part No		PAR #:	Fault Cate	gory:	NCR: Yes	No DQA :	Date: _	
		esolution:						
NCR:			WORK ORDE	ER NON-CONFORMA	NCE (NCF	(1)		
DATE	STEP	Description of NC Section A	Corrective Action Section		n B	Verification	Approval	Approval
			Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
7-1-7-0								
								,



